

Certificate

Registration No.: PV 50279017

Page 1

Report No.: 15049682.002

License Holder:

YINGLI ENERGY (CHINA) COMPANY LIMITED
No. 3399 Chaoyang North Road
Baoding, Hebei 071051
P. R. China

Product:

PV Modules

Type:

With 6" poly c-Si solar cell:

YLxxxP-23b (xxx=150-210, in increments of 5, 48 cells)

YLxxxP-26b (xxx=180-240, in increments of 5, 54 cells)

YLxxxP-29b (xxx=200-265, in increments of 5, 60 cells)

YLxxxP-32b (xxx=220-290, in increments of 5, 66 cells)

YLxxxP-35b (xxx=235-320, in increments of 5, 72 cells)

Manufacturing Plant:

YINGLI ENERGY (CHINA) COMPANY LIMITED
No. 3399 Chaoyang North Road
Baoding, Hebei 071051
P. R. China

Basis:

IEC 61701:2011
"Salt mist corrosion testing of
photovoltaic (PV) modules"

Factory Inspection
To document the consistent quality of
the product, factory inspections are
performed periodically.



www.tuv.com
ID 0000024426

Remarks:

- Valid in conjunction with TÜV Rheinland certificate PV 50278940 Page 1- 2 and **only** for the material combination as listed in the above mentioned test report.
- Test performed with **severity 6** of 6.
- This certificate includes further manufacturing plants as listed on Attachment List of Factories.


Conditions:

The product test is voluntarily according to technical regulations. Any change of the design, materials, components or processing may require the repetition of some of the qualification tests in order to retain type approval.

The certificate is valid until 20 March 2019.



Certification body



Dipl.-Ing (TU) Gerd Reimann

24 March 2014

Attachment of Certificate

PV 50279017 001

List of factories:

- 1 YINGLI ENERGY (CHINA) COMPANY LIMITED
NO.3399 Chaoyang North Road
Baoding, Hebei 071051
P. R. China

Inspection report no.: 15036290.004

- 2 BAODING TIANWEI YINGLI NEW ENERGY RESOURCES CO., LTD
NO.3399 Chaoyang North Road
Baoding, Hebei 071051
P. R. China

Inspection report no.: 15036290.004

- 3 HAINAN YINGLI NEW ENERGY RESOURCES CO., LTD
Shiziling Industrial Park of Haikou
National Hi-Tech Industrial Development Zone
Haikou 571100
P. R. China


Inspection report no.: 15038572.004

- 4 Tianjin Yingli New Energy Resources Co., Ltd.
Tianjin Ninghe Modern Industry Area
Tianjin 301510
P. R. China

Inspection report no.: 15049639.002



Certification body



Dipl.-Ing. (TU) Gerd Reimann

24 March 2014